

**From:** Leslie Heppler  
**To:** coxtrans@manti.com  
**Date:** 4/10/2008 12:45:43 PM  
**Subject:** Inspection report S0230096

Brent Cox -

Please see the attached Inspection Report. If you have any questions, please feel free to call me at 801-538-5257

Leslie Heppler  
Utah Division of Oil, Gas & Mining  
(801) 538-5257 (Mon thru Thur)  
[lhopper@utah.gov](mailto:lhopper@utah.gov)

**CC:** Lynn Kunzler; Penny Berry; Susan White



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

**Inspection Report**

Supervisor \_\_\_\_\_

**DRAFT**

**Minerals Regulatory Program**  
**Date of Report:** 04/10/2008

**Mine Name:** Quarry (Little Salt Creek Gypsum)  
**Operator Name:** Cox Transport Incorporated

**Permit number:** S0230096  
**Inspection Date:** 04/09/08  
**Time:** 11:00 am

**Inspector(s):** Leslie Heppler, Dan Smith  
**Other Participants:** none  
**Mine Status:** NOT BONDED

**Weather:** Sunny and cold

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:** This was a routine inspection

**Inspection Summary:** Bond has not been received. New disturbance is greater than 1 acre, proposed bond is only for 1 acre; Escalation Fee for 2008 will apply. Actively mining stockpiles and hauling product, (see attached photos). No erosion control, concurrent reclamation or water impoundments were noted on site.

**Conclusions and Recommendations:** Operator has 30 days to comply with all local, state and federal rules. DOGM Assessment Officer and BLM field office has been notified of Inspection Report. Notice of Violation will be forthcoming if compliance to rules is not completed.



**Inspector's Signature** \_\_\_\_\_ **Date:** \_\_\_\_\_

Page 2 of 2

Inspection Date: 04-03-08; Report Date: 04-08-08  
Mine Number M0450027

**DRAFT**

Photos Taken 04-09-08



tah:pb

cc: Susan White, Lynn Kunzler  
Brent C. Cox  
BLM - Fillmore  
GPS map and Photos

P:\GROUPSMINER ALSIWPM\023-Juab\IS0230096-Quarry\inspections\ins\_p-s0230096\_04-09\_-08.doc